

Dear Asbestos Customer:

Be advised that all deliveries of Asbestos must be accompanied by a CCSWA Asbestos Manifest.

The manifest must be properly completed with all required information prior to arriving at the scalehouse. Loads of asbestos waste accompanied by improperly completed manifests will not be accepted for disposal at Lanchester.

Manifests must be completed as follows:

- Line #1 The location where the asbestos is generated. This includes the street address, town and zip code.

- Line #2 The name of the person or company who owns the property in line #1. Authorized representative is a representative of the owner who is familiar with the removal project.

- Line #3 The name and complete address of the asbestos abatement contractor responsible for the removal.

Operator's Certification should be the signature of the generator's authorized agent who is certifying the waste is properly packaged for transport.

- Line #4 Place a check mark next to the box identifying what type of asbestos and note the volume.

- Line #5 Transporter name and driver signature.

- Line #6 This section will be completed by the weighmaster after the waste has been disposed of at the landfill.

- Line #7 This section is for any comments by the disposal site.

All copies of the manifest must accompany the load to the landfill. A signed copy of the manifest will be returned by mail to the Generator. The Transporter will receive a signed copy after disposal at Lanchester.